



EPL No: 11438
 Date: 23/02/2026

Date	Time	Method	EPA Ref	Type	Location	Proximity to Site	Description	Wind Rose Chart/Map	Av. Wind Speed (m/s)	Av. Wind Direction	Bar. Pressure (hPa)	Temp10m Av (°C)	Activity on site consistent with normal operation?	Action taken or proposed to be taken to deal with the incident and/or prevent a recurrence	Photograph of active landfill cell showing intermediate cover (closest to complainant date) [1]	Current level of leachate in each pond at most the most recent survey	Daily H2S Non Zero Value Average (PPB)	Mechanical evaporator run times on ondate of odour complaint	Correlation with wind direction (Y/N)	Conclusion
21/2/2026	2041	Website Feedback Form		Odour	Taylor's Creek, Tarago	~5km	The complainant notes a "Chemical smell and garbage smell. Odour intensity: 6 - Unpleasant to remain in the area. Yet another still day when it would be perfect to have breakfast outside instead it is not possible because of the guests."		4.5	E	923	20	Yes	Increased hydration of the landfill cover to prevent surface tracking. An assessment of meteorological data and operational activity will be completed in order to investigate the potential source or cause of odour was undertaken. An odour complains report will be completed and made publicly available on the Woodlawn reports page. A 12 month trial using a tarp as cover on the ATF has commenced.		ED3N1 791-23 ED3N2 791-23 ED3N3 791-23 ED3N4 791-23 ED3S2 792-39	42	5:45am -7:15pm	Y	An assessment of meteorological data and operational activity has been completed in order to investigate the potential source or cause of odour was undertaken with no significant impacts evident at the time of the complaint. Veolia acknowledges that the premises is potentially the source of the odour detected by the complainant based on wind direction. It is noted that H2S was detected at the monitoring stations on site on this date 8 February 2026.
20/2/2026	1320	EPA Environmental Line		Odour	Not provided		The complainant notes a "stinking rotten garbage smell coming from Veolia Woodlawn. The odour started at 08:00 and is still present. Caller finding hard to work outdoors."		3.7	NE	927	18	Yes	Increased hydration of the landfill cover to prevent surface tracking. An assessment of meteorological data and operational activity will be completed in order to investigate the potential source or cause of odour was undertaken. An odour complains report will be completed and made publicly available on the Woodlawn reports page. A 12 month trial using a tarp as cover on the ATF has commenced.		ED3N1 791-23 ED3N2 791-23 ED3N3 791-23 ED3N4 791-23 ED3S2 792-39	0	5:45am -7:15pm	N	No location provided

Licensee:
 Veolia Environmental Services (Australia) Pty Ltd
 Cnr Urwin & Shirley Streets, Roskill NSW 2142

Permit:
 Woodlawn Landfill
 Collector Road, Tarago NSW 2580

[1] Photo