



EPL No:		11436																																							
Date:		02/10/2024																																							
Date	Time	Method	EPA Ref	Type	Location	Proximity to Site	Description	Wind Rose Chart/Map	Avg Wind Speed (m/s)	Avg Wind Direction	Bar Pressure (hPa)	Temp10m Avg (°C)	Activity on site consistent with normal operation?	Action taken or proposed to be taken to deal with the incident and/or prevent a recurrence	Photograph of active landfill cell showing intermediate cover (closest to complainant data) [1]	Current level of leachate in each pond at most the most recent survey	Daily H2S Non Zero Value Average (PPB)	Mechanical evaporator run times on ondate of odour complaint	Correlation with wind direction (Y/N)	Conclusion																					
26/09/2024	08:00	EPA Environmental Line	Odour	REF 33131	Collector Road Tarago	Approximately 8 km East of the site	Notifier reported the following odour: "smell of rubbish coming from the site. Caller advised that this is an ongoing issue, that has been going on for over a year. Caller advised that they have reported the issue continually to the EPA. Caller advised that they are approximately 11 km from property to the site. Advised that the smell travels when the weather is still in terms of wind. Caller advised that they are wanting this to be investigated as it is ongoing. Incident Still Occurring : YES *8am 26 September 2024.		4.563	East South Easterly winds Complainant not downwind of the premises.	928.112		Y	The Odour Limit has completed a gas characterisation assessment to determine the presence of other odour gases. A copy of the assessment can be found on the Woodlawn Weillage under 'H2S Monitoring'. Veolia has received approval to undertake a trial utilising alternate methods of covering the tip face. Veolia will continue to implement the recommendations within the 2023 Odour Audit.		Date: 12/09/2024 ED3N-1: 792.06 ED3N-2: 792.06 ED3N-3: 792.06 ED3N-4: 791.57 EO3S-5: 793.64	Point 9 - 0 Point 71 - 0 Point 72 - 0	5:00am - 6:00pm	Y	An assessment of meteorological data and operational activity has been completed in order to investigate the potential source or cause of odour was undertaken with no significant impacts evident at the time of the complaint. Veolia acknowledges that the premises is potentially the source of the odour detected by the complainant, however based on the wind direction at the time of the complaint it is unlikely. It is noted that H2S was not detected at the monitoring station on site or within Tarago on 26/09/2024.																					
Licensee:																																									
Veolia Environmental Services (Australia) Pty Ltd Cnr Unwin & Shirley Streets, Rosehill NSW 2142																																									
Premises:																																									
Woodlawn Landfill Collector Road, Tarago NSW 2580																																									

[1] Photo