
EPL No:	11436
Date:	02/11/2026

Date	Time	Method	EPA Ref	Type	Location	Proximity to Site	Description	Wind Rose Chart/Map	Av_Wind Speed (m/s)	Av_Wind Direction	Bar_Pressure (HPa)	Temp10m_Av (°C)	Activity on site consistent with normal operation?	Action taken or proposed to be taken to deal with the incident and/or prevent a reoccurance	Photograph of active landfill cell showing intermediate cover (closest to complaint date) [1]	Current level of leachate in each pond at most the most recent survey	Daily H2S Non Zero Value Average (PPB)	Mechanical evaporator run times on ondate of odour complaint	Correlation with wind direction (Y/N)	Conclusion
1/11/2026	19:38	Website Feedback Form		Odour	Taylors Creek, tarago	~5km South West of site	Complainant reported strong chemical smell of odour intensity 6 out of 6 - The smell burns the back of my throat adn makes my eyes sting. I cough and dry reach.		4.53	WNW	924.09	16.48	Yes	Increased hydration of the landfill cover to prevent surface cracking. An assessment of meteorological data and operational activity will be completed in order to investigate the potential source or cause of odour was undertaken. An odour complains report will be completed and made publicly available on the Woodlawn reports page. A 12 month trial using a tarp as cover on the ATF has commenced.		ED3N1 791.42 ED3N2 791.42 ED3N3 791.42 ED3N4 791.71 ED3S2 793.12	0	5:45am -7:15pm	N	An assessment of meteorological data and operational activity has been completed in order to investigate the potential source or cause of odour was undertaken with no significant impacts evident at the time of the complaint. Veolia acknowledges that the premises is potentially the source of the odour detected by the complainant. It is noted that the wind direction at the time of the complaint was not consistent with the location of the complainant, and that H2S was not detected at the monitoring station on site on morning of 01 November 2026.

Licensee:
Veolia Environmental Services (Australia) Pty Ltd Cnr Unwin & Shirley Streets, Rosehill NSW 2142

Premises:
Woodlawn Landfill Collector Road, Tarago NSW 2580

[1] Photo